


Post-operative complications: mechanical problems



2 patients underwent replacement of the pump of the AMS-800
2 patients underwent replacement of the cuff of the AMS-800
1 patient underwent replacement of the reservoir of the AMS-800